ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0159, W0166, W0234	NA	Sidedahalli
Segment No.	**Total Length (m)**	
14/C-W0159/S010048	43.50	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	43.50	77.496908	13.063375	77.496876	13.063767	Main road	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Cement concrete road at INSIGHT SCHOOL in NMH Extension 2nd cross road in Ward No 14 Bagalagunte	500000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Others	CC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		014-19-000001
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/398/18-19	08/03/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
08/03/2019	07/03/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Sri Lakshmi Ganapathi Developers		483025.00
Phone No.	**E-Mail ID**	
9972216255		

Field Inspection Details

Number of Trees	Any Other Information	Name
2	CC Drain	Chetan KM
Date of Inspection	**Remarks**	
17/12/2020	work completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	EE DAS	25/01/2021		Completed
AEE	M B Jayakumar	17/12/2020	16/01/2021	Work Completed
AE	Chethan K M	17/12/2020	16/01/2021	COMPLETED
AE	Chethan K M	17/12/2020	16/01/2021	Completed

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0159, W0166, W0234